












Agrometall - přední radlice

Obrázek	Typ	Označení	Výkon nosiče (hp)
	OR-L	OR L 1000	20 - 35
		OR L 1200	
		OR L 1400	
		OR L 1500	
		OR L 1600	
	OR-M	OR M 1100	30 - 65
		OR M 1300	
		OR M 1500	
		OR M 1600	
		OR M 1800	
		OR M 2000	
		OR M 2300	
OR M 2500			
	OR-T2	OR T2 2200	60 - 120
		OR T2 2400	
		OR T2 2600	
	OR-T1	OR T1 2200	60 - 120
		OR T1 2400	
		OR T1 2600	
		OR T1 2800	
	OR-T	OR T 2500	120 - 200
		OR T 3000	
	OR-P	OR P 3000, K	120 - 200
		OR P 3200, K	
		OR P 3500, K	
		OR P 3000	
		OR P 3200	
		OR P 3500	

Agrometall - pluchy

Obrázek	Typ	Označení	Výkon nosiče (hp)
	SR-L	SR L 1000	20 - 35
		SR L 1100	
		SR L 1200	
		SR L 1400	
		SR L 1600	
	SR-M	SR M 1500	30 - 65
		SR M 1800	
		SR M 2000	
	SR-T2	SR T-2 2200	60 - 120
		SR T-2 2400	
		SR T-2 2600	
		SR T-2 2800	
	SR-T1	SR T-1 1800	60 - 120
		SR T-1 2000	
		SR T-1 2200	
		SR T-1 2400	
		SR T-1 2600	
	SR-T	SR T 2500	120 - 200
		SR T 3000	